

FUEL PUMP TECHNICAL BULLETIN

PRODUCT SERVICE BULLETIN

NO. 090111

Prior to determining whether or not the replacement fuel pump or assembly is not working properly, it is recommended that the fuel pump relay be tested. On some vehicles this may be easily accomplished by swapping the fuel pump relay with the A/C relay (or another equally rate amperage relay). Other vehicles may require that an exact replacement relay be installed.

Consult the vehicle repair manual for alternative relay test procedures.

ON GM Vehicles it is particularly important to check the female electrical connection in the relay block (under the relay) for burned, melted, or corroded connections as these conditions may occur when the original pump fails. Replacing the relay may not resolve the problem if these connections have been damaged as well.